


Sockets and accessories


GZ14

For R15 - 4 CO


Screw terminals
Max. tightening moment
for the terminal: 0,7 Nm
On panel mounting
96,8 x 46,4 x 24,5 mm
Four poles
10 A, 250 V AC




Connection diagram



Mounting dimensions



Dimensions



Accessories

GZ14 0737


GZ14Z

For R15 - 4 CO


Screw terminals
Max. tightening moment
for the terminal: 0,7 Nm
On panel mounting, behind
92,2 x 46 x 24,5 mm
Four poles
10 A, 250 V AC



Connection diagram




Mounting dimensions



(screw terminals side view)

Dimensions



Accessories


GZ14 0737

GZ14P


For R15 - 4 CO

Push-in terminals
Max. cross section of the cables:
2 x 2,5 mm² (ferrules without insulation)
2 x 1,5 mm² (ferrules with insulation)
Stripping length: 10 mm


On panel mounting, behind
92,2 x 46,2 x 44,7 mm
Four poles
10 A, 250 V AC



Connection diagram




Mounting dimensions



(Push-in terminals side view)

Dimensions



Accessories

GZ14 0737